



Environmental Protection Agency

4500 S. Sixth Street Springfield, IL. 62706

Ph. (217) 786-6892

October 14, 1981

Refer to Macon Co /LPC -- #11580101
Decatur/Waste Hauling

RECEIVED

OCT 14 1981

EPA Region 5 Records Ctr



351004

EPA — DLPC
STATE OF ILLINOIS

Mr Jerry Camfield
Waste Hauling, Inc
129 Wyckles Road
Decatur, Illinois 62522

Dear Mr Camfield

Your solid waste disposal facility located west of Decatur was inspected on October 8, 1981, by David C Jansen, representing this Agency

At the time of the above inspection you s
Mr Jansen that, according to plan sheets in your possession, the north berm was not required to be above the top of the fill. As Mr Jansen was not then in possession of a plan sheet depicting a cross section of this fill area and the north berm, he concurred with your opinion, and a permit violation for allowing the fill to be brought above the top of the berm was not marked on the enclosed inspection report. Mr Jansen has since obtained and reviewed a copy of the plan sheet showing the above cross section. This plan sheet depicts the top of the north berm at final fill elevation. Therefore, the north berm must be so constructed such that the fill is no longer higher than the top of the berm in accordance with your approved plans, specifications, and Operating Permit #1973-41.

Mr Jansen will contact you before his next inspection of your site so that this matter can be discussed further.

If you have any questions, please contact us

Sincerely,

Monte M Nienkerk
Central Region Manager
Land Field Operations Section
Division of Land/Noise Pollution Control

MMN/DCJ/cp
Enclosure

cc DLPC/Division File
DLPC/FOS, Central Region
Macon Co Health Dept